## **APPENDIX 2**

## **12 Arthur Street OFFICE Repairs and Works**

Repair Work to be carried out			COST	RUNNING TOTAL		
Internal paintwork		£	19,200			
Damp and plaster remedial work		£	6,000			
Kitchen Units		£	3,000			
Gas Alterations		£	1,000			
Carpets		£	8,000			
Fire and Intruder Alarms		£	2,000			
Window and Door Repairs (see below)		£	7,000			
Sanitary ware replacement		£	3,000			
2nd Floor Kitchen		£	3,000			
External Roof Repairs		£	2,500			
Signage and additional emergency lighting		£	1,500			
External decoration and repairs		£	9,000			
Clear rear garden and rear fence repairs		£	500			
	sub TOTAL	£	65,700	£ 65,700		

DDA work to be carried out	COST		RUNNING TOTAL
Disabled toilet constructed within existing floor plan	£	5,000	
Internal ramp and widening doors for disabled access to ground			
floor from front door to rear garden	£	8,500	
Form Office	£	8,000	
sub TOTAL	£	21,500	£ 87,200

EPC UPGRADE WORK		COST	RUNNING TOTAL		
Remove existing windows and upgrade to Double glazed Upvc					
Units	£	12,500			
sub TOTAL	£	12,500	£ 99,700		

ASBESTOS WORK	COST		RUNNING TOTAL		
Removing asbestos faced partition between toilets and					
rebuilding removed partitions	£	2,500			
sub TOTAL	£	2,500	£	102,200	

ADJUSTMENTS			COST	RUNNING TOTAL
Window and Door Repairs DEDUCT		£	7,000	
Door Repairs Only ADD		£	2,000	
	sub TOTAL	-£	5,000	£ 97,200

CONTINGENCY	COST		TOTAL	
Contingency (min 10%)	£	10,220	£	107,420
Contingency (max 15%)	£	15,330	£	112,530